CORRES. CONTRO	L			
<b>OUTGOING LTR. NO</b>	).			
DOE ORDER #.				
DOC ORDER #.	-			
	,			
98-RFO1616	9			
DIST.	LTR	ENC		
BENSUSSEN, STAN	$\top$	<del>                                     </del>		
BORMOLI NI, ANN	+	+		
BRAILSFORD, MARV	+	+		
BURDGE, LARRY	╁	╅—		
CARD, BOB	+	<del>                                     </del>		
HARDING, WYNN	┿	┼─		
HILL, JOHN	+	+		
MARTINEZ, LEN	<del> </del>	+		
PARKER, ALAN	-	<del> </del>		
TILLER, ROBERT	<del> </del>	—		
TUOR, NANCY	-	<del> </del>		
VOORHEIS, GARY	1	—		
VOORHEIS, GARY				
		匚		
Crowe, Steve				
ledahi, Tim		1		
Rodgers, Alan	IX	$\times$		
	1, -	<del>                                     </del>		
	1	_		
Indones See	╄	—		
inderson, Scott				
Jutier, Lane	X_	$\succeq$		
reengard, Tom	$\times$	<u> </u>		
lahn, Steve	L.	ľ		
lickle, Gordon				
ennedy, Colburn		П		
ahoud, Russ				
hland, Jennifer	1			
		1		
	1			
****	<del>                                     </del>	<del></del>		
****		─		
	╌	<del></del>		
	<del>-</del>	<del> </del>		
	<del>                                     </del>	<del>-</del>		
	<del>                                     </del>	<del> </del>		
		<del></del>		
	-			
	<del> </del>	<del></del>		
	├			
	├	<b>—</b>		
	<del> </del>	<b></b>		
	<u> </u>			
		L		
75077 88 ··				
ORRES.CONTROL	X	X		
DMIN RECRD/116	X	X		
ATS/1130G	Ľ	/		
CLASSIFICATION:				
CNI				
NCLASSIFIED	$\vdash$			
ONFIDENTIAL	$\vdash$	<del>-</del>		





98-RF-01616

March 27, 1998

Norma Castaneda

ES&H Program Assessment

DOE, RFFO

TRANSMITTAL OF THE TRAINING REQUIREMENTS FOR THE TRENCH 1 SOURCE **REMOVAL PROJECT - TCG-009-98** 

The purpose of this correspondence is to communicate the managerial/oversight personnel training requirements for the Trench 1 Source Removal Project (draft transmittal letter to EPA and CDPHE is attached). As shown in Attachment 1, there are different training requirements for access to the Contamination and High Contamination Areas, Radiological Buffer Areas, and the Support Zone. For project specific courses offered by RMRS, please contact Brandon DiSalle at 966-3735 so that your name(s) can be added to the list of attendees. You will be notified when project-specific courses are scheduled. Radiation Worker II can be scheduled by calling 966-2743. It is offered at Building 060.

The General Employee Radiation Training (GERT), Hearing Conservation, and Respirator Indoctrination courses are computer-based training (CBT) and are located at T130E. They can be scheduled by calling 966-6473. Instructions for the respirator fit chamber certification will be provided following the Respirator Indoctrination course. The two Respirator Protection Training courses will be scheduled together.

T. C. Greengard

Waste & Remediation Operations

TCG:bag

Orig. and 1 cc - N. Castaneda

SIGNATURE:

kempt per CEX-266-95

ECRET

I REPLY TO REP CC NO .:

UTHORIZED CLASSIFIER

Attachments: As Stated (2)

ACTION ITEM STATUS: PARTIAL/OPEN

CLOSED

LTR APPROVALS:

ORIG. & TYPIST INITIALS:

5469 (Rev. 3/98)

TCG :bag Kaiser-Hill Company, L.L.C.

Courier Address: Rocky Flats Environmental Technology Site, State Hwy. 93 and Cactus, Rocky Flats, CO 80007 • 303.966.7000

Mailing Address: P.O. Box 464, Golden, Colorado 80402-0464

BZ-1108-A-00023

## Attachment 1 Training Summary

Required Training (Course Number)	Contamination Area/High Contamination Areas (Exclusion Zone)	Radiological Buffer Areas (Contamination Reduction Zone)	Project Support Zone
Daily Health and Safety Briefing (NA)	Χ¹	X1	X1
General Employee Radiation Training (019-278-01)			X
Hazard Com. Work Area Indoctrination (019-750-03)	X1	X1	ΧI
Hearing Conservation (071-400-01)	X	X	
HSP-21.04 Briefing (NA)	X1	X1	X1
Medical Surveillance (056-86-15)  • Respirator, negative pressure  • Respirator, PremAire or SCBA  • PPE clothing, Level B  • Thermal Hot Environment Work  • Nuclear Work  • Hearing Conservation	X	Х	
OSHA 40 - Hour (018-691-19)	X	X	
OSHA 8 - Hour (018-691-05)	X	X	
OSHA 3 - Day On Site Supervision (018-691-07)	X1	X1	X1
Pre-Evolution Briefing (NA)	X1	X1	X1,2
Radiation Worker II (023-484-00)	X	X	
Respirator Indoctrination (056-284-01)	X	X	
Respirator Fit Chamber Certification (056-284-02)	X	X	
Respirator Protection Training - MSA 4500II (TBD)	ΧI	X1	
Respirator Protection Training - PremAire (012-931-01)	X1	X1	
Uranium Facilities Training (TBD)	X1	Χı	

<sup>&</sup>lt;sup>1</sup> Provided by RMRS

<sup>&</sup>lt;sup>2</sup> Short-term visitors to the site may receive a Visitor Orientation in lieu of the Pre-Evolution Briefing

DRAFT

DRAFT

DRAFT

Tim Rehder
United States Environmental Protection Agency
Rocky Flats Project
999 18<sup>th</sup> Street, Suite 500
Denver, CO 80202-2466

TRANSMITTAL OF THE TRAINING REQUIREMENTS FOR THE TRENCH T-1 SOURCE REMOVAL PROJECT

The purpose of this correspondence is to communicate the managerial/oversight personnel training requirements for the Trench 1 Source Removal Project. As shown in Attachment 1, there are different training requirements for access to the Contamination and High Contamination Areas, Radiological Buffer Areas, and the Support Zone. You will be notified when project-specific courses are scheduled. Radiation Worker II can be scheduled by calling 966-2743. It is offered at Building 060. For project specific courses offered by RMRS, please contact Brandon DiSalle at 966-3735 so that your name(s) can be added to the list of attendees.

The General Employee Radiation Training (GERT), Hearing Conservation, and Respirator Indoctrination courses are computer-based training (CBT) and are located at T130E. They can be scheduled by calling 966-6473. Instructions for the respirator fit chamber certification will be provided following the Respirator Indoctrination course. The two Respirator Protection Training courses will be scheduled together.

Steve Slaten, Manager Regulatory Liaison

Attachment: As Stated

CC:

Steve Gunderson - CDPHE